Sidlesham Infiltration Plan

Appendix A – Status of Planned Actions August 2025






Summary of work completed

Action	Km of sewer
Length Surveyed by CCTV	54.31
Length Surveyed by Electroscan	8.53
Length with no work required	51.36
Length Sealed	4.71
Length to be sealed	6.77
Manholes sealed	9
Manholes to be sealed	3


Reporting Year	Surveyed (km)	Sewers Sealed (km)	Manholes Sealed
Pre 2014	40.5	0.3	7
2014	0.2	0.2	0
2015	0.2	0.1	0
2016	4.8	0.1	0
2017	3.2	1	0
2018	4.5	0.2	2
2019	0.3	0.6	0
2020	0	0.1	0
2021	0	0m	0
2022	9.1	0.1	0
2023	0	0m	0
2024	0	2	0
Post 2024	0	6.7	3
2025	0.53	3.38	0






Reference Plan






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation. The use of storm harvester data will be used at some point in the future to target inspections and find infiltration






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.





Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.
The use of storm harvester data will be used at some point in the future to target

inspections and find


infiltration






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.






Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.





Note – sewers shown as surveyed by cctv or electro scan with no corresponding sealing work have been determined to not require rehabilitation.






Birdham Sewer Sealing

Sewers sealed





Itchenor Sewer Sealing

Sewers sealed

