

Test Surface Water Drought Permit

2.2_MMP Appendix 2b

Water Quality Monitoring – Redacted Locations

19 July 2022



from
**Southern
Water** 

Contents

Contents	2
1 Water Quality Monitoring sites	3
Table 1 Location and period in operation	3

Water Quality Monitoring – Redacted Locations

1 Water Quality Monitoring sites

Figure 1 in document ref: **2.2_Monitoring and mitigation plan** shows a map of the location of the permanent WQ installations in the Lower Test Area. The Site locations are detailed in Table 1 below.

Table 1 Location and period in operation

Site Location	Site Code	Installed by HLS				Installed by Meteor		Comments
		Easting	Northing	Start	End	Easting	Northing	
River Test catchment								
Romsey Bypass	RT1	Redacted	Redacted	19 Jul 18	25 Oct 21	Redacted	Redacted	Meteor installed 1 Apr 21
U/s M27	RT2	NA				Redacted	Redacted	Meteor installed 1 Apr 21
Redbridge	RT3	Redacted	Redacted	21 Sep 18	1 May 21	Redacted	Redacted	Meteor installed 22 Apr 21
East Channel	LT3	Redacted	Redacted	1 Sep 18	1 Mar 19	Redacted	Redacted	Meteor installed 5 Aug 21 – 25 Aug 21 vandalised 3 times, no further installation
Nr Southampton RFC				6 Sep 19	27 May 20			
River Blackwater catchment								
U/s M27	BFFC1	Redacted	Redacted	19/ Jul 18	30 Aug 21	Redacted	Redacted	Meteor installed 9 Nov 21
Broadlands Lake	BW1	Redacted	Redacted	19/ Jul 18	24 Oct 21	Redacted	Redacted	Meteor installed 9 Nov 21 Vandalised 23 Feb 22
Little Testwood Lake	BW2	Redacted	Redacted	19/ Jul 18	1 May 21	Redacted	Redacted	Meteor installed 1 May 21
Testwood WSW – not part of S20 programme								
Intake	TW Intake	Redacted	Redacted	NA	Ongoing			Installed and maintained by SWS
U/S Discharge	TW U/S					Redacted	Redacted	Installed 18 Jan 21 to monitor discharge during works on site
D/S Discharge	TW D/S					Redacted	Redacted	

N.B. NGRs can be provided on request subject to confidentiality agreement