
## Winchelsea Beach Infiltration Plan

Appendix A – Status of Planned Actions - August 2025








## Reference Plan

Action	Km
Length Surveyed (CCTV)	4.36
Length Surveyed (Electroscan)	1.62
Length with no work required	1.20
Length Sealed	3.32
Length to be sealed	0.474
Manholes sealed	4
Manholes to be sealed	1






## Detailed plan 1

Note – sewers shown as surveyed by cctv or Electroscan (green line) with no corresponding sealing work have been determined to not require rehabilitation.

The use of storm harvester data will be used at some point in the future to target inspections and find infiltration





## Detailed plan 2

Note – sewers shown as surveyed by cctv or Electroscan (green line) with no corresponding sealing work have been determined to not require rehabilitation. The use of storm harvester data will be used at some point in the future to target inspections and find infiltration

